


# BOW MAR W&S DISTRICT

## Water Pipe Installed By Year






	4.00		6.00			8.00		10.00		12.00			Total
	CAST IRON PIPE	POLYVINYL CHLORIDE PIPE	CAST IRON PIPE	DUCTILE IRON PIPE	POLYVINYL CHLORIDE PIPE	CAST IRON PIPE	POLYVINYL CHLORIDE PIPE	CAST IRON PIPE	POLYVINYL CHLORIDE PIPE	CAST IRON PIPE	DUCTILE IRON PIPE	POLYVINYL CHLORIDE PIPE	
<b>2015</b>	0	0	0	26	62	0	1,835	0	16	0	0	0	1,938
<b>2022</b>	0	0	0	34	0	0	939	0	0	0	0	0	973
<b>Total</b>	<b>804</b>	<b>843</b>	<b>2,327</b>	<b>2,388</b>	<b>9,433</b>	<b>3,011</b>	<b>22,634</b>	<b>1,037</b>	<b>367</b>	<b>936</b>	<b>92</b>	<b>2,644</b>	<b>46,514</b>

3/2/2023

# BOW MAR W&S DISTRICT

## Sewer Pipe Installed By Year



# Sewer Pipe Installed By Year

	6		8		Total
	Verified Clay Pipe	CURED IN PLACE PIPE	Polysulfide Chloride	Verified Clay Pipe	
1962	0	0	0	258	258
1964	0	0	0	7,550	7,550
1966	0	0	0	1,779	1,779
1967	90	0	0	4,145	4,235
1968	0	0	0	801	801
1969	413	0	0	9,771	10,185
1971	316	0	0	8,529	8,845
1972	0	0	0	3,636	3,636
2005	0	0	160	0	160
2011	0	775	0	0	775
2014	0	0	161	0	161
<b>Total</b>	<b>819</b>	<b>775</b>	<b>321</b>	<b>36,468</b>	<b>38,383</b>